

30-NOV-01

MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

TABLE OF CONTENTS

PROBLEM NUMBER	DESCRIPTION	PAGE NUMBER
<u>INDEXES</u>		
	EQUIPMENT INDEX	ii
	ACTION INDEX	iii
	ORIGINATORS INDEX	iv
	DUE DATE SUMMARY	vi
 PROBLEMS		
<u>14770</u>	ROCKET MOTOR IGNITOR CABLE FRAYED AND BARE WIRES EXPOSED.....	1
<u>14963</u>	DAMAGED DOME.....	3
<u>15435</u>	SHEARED GROUNDING PIN.....	7
<u>15483</u>	WEAPON DROPPED DUE TO HOIST FAILURE.....	9
<u>15644</u>	WEAPON DAMAGED DURING HANDLING.....	13
<u>16308</u>	SHATTERED IR DOME.....	15
<u>16946</u>	MISSILE DAMAGED DUE TO WATER CONTAMINATION.....	17

NOTE: OPEN problems denoted by asterisk (*) following problem number.

30-NOV-01

**MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 14770

CLOSED

	NOMENCLATURE	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	GUIDED MISSILE, MAVERICK	3384304-101	1410	01-158-2872	PB69
	GUIDED MISSILE, MAVERICK	3647135-100	1410	01-253-8073	PD63
	GUIDED MISSILE, MAVERICK	3647136-100	6920	01-254-7577	PY15

EI CNTRL NO:

PROB BRIEF : ROCKET MOTOR IGNITOR CABLE FRAYED AND BARE WIRES EXPOSED

PROBLEM DESCRIPTION : This problem addresses incidents in which Rocket Motor Ignitor Cables were discovered to be frayed, often having bare wires exposed.

PREVENTIVE ACTION : Adherence to established ordnance handling procedures will preclude incidents of this nature. Use of due and proper care would have prevented these mishaps.

CORRECTIVE ACTION : There is no corrective action other than repair of the damaged units.

	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS	
OCCURRENCES:	USS LINCOLN (CVN-72)	CODR	R21297-00-0824	22NOV00	CLOSED	
	VFA-83	CODR	V09223-99-0017	21JUL99	CLOSED *	
	USS ENTERPRISE (CVN-65)	CODR	R03365-99-0021	24MAR99	CLOSED *	
	USS NIMITZ (CVN-68)	CODR	R03368-97-0012	26OCT97	CLOSED *	
	VFA-94	CODR	R09295-96-0049	26NOV96	CLOSED *	
	USS WASHINGTON (CVN-73)	CODR	V21412-96-0024	29JUN96	CLOSED *	
	USS WASHINGTON (CVN-73)	CODR/EIR	V21412-96-0004	19FEB96	CLOSED *	
	VA-165	CODR	R09616-96-0003	15FEB96	CLOSED *	
	USS NIMITZ (CVN-68)	CODR	R03368-96-0004	06FEB96	CLOSED *	
	VFA-192	CODR	R09076-95-0011	18OCT95	CLOSED *	
	VA-115	CODR	R09604-95-0031	10SEP95	CLOSED *	
	VP-26	CODR	V09610-95-0011	08MAR95	CLOSED *	
	NAS SIGONELLA	CODR	N62995-94-0004	31OCT94	CLOSED *	
	VP-10	CODR	V09639-94-0023	18OCT94	CLOSED *	
	NAS SIGONELLA	CODR	N62995-94-0003	08AUG94	CLOSED *	
	USS VINSON (CVN-70)	CODR	R20993-94-0017	14MAY94	CLOSED *	
	USS VINSON (CVN-70)	CODR	R20993-94-0015	06MAY94	CLOSED *	
	VFA-25	CODR	R09637-94-0023	28APR94	CLOSED *	
	VFA-195	CODR	R09706-93-0062	29DEC93	CLOSED *	
	VFA-195	CODR	R09706-93-0061	23DEC93	CLOSED *	
	VA-85	CODR/EIR	V09225-93-0075	14NOV93	CLOSED *	
	USS NIMITZ (CVN-68)	CODR	R03368-93-0005	25APR93	CLOSED *	

* ACTION REPORTED IN PREVIOUS PUBLICATION

30-NOV-01

**MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 14770

(Continued)

SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
VA-165	CODR	R09616-93-0026	25APR93	CLOSED *
NWS FALLBROOK	PQDR II	N00396-92-0032	18SEP92	CLOSED *
USS KENNEDY (CVN-67)	PQDR I	V03367-92-0035	26JUL92	CLOSED *
USS EISENHOWER (CVN-69)	EMR	V03369-91-0012A	17DEC91	CLOSED *
USS LINCOLN (CVN-72)	EMR	V21297-91-0008	08JUL91	CLOSED *

*** ACTION REPORTED IN PREVIOUS PUBLICATION**

ACTION : USS LINCOLN (CVN-72) CODR R21297-00-0824 22NOV00 CLOSED

END ITEM	PART/DOC. NO.	FSC	NIIN	NALC
	3647135-100	1410	01-253-8073	PD63
NOMEN: GUIDED MISSILE, MAVERICK				
S/N: 6700569				
FAILED PART:	3647135-100	1410	01-253-8073	PD63
NOMEN: GUIDED MISSILE, MAVERICK				
S/N: 6700569				
END ITEM :				
	S/N: 6101515, 6101343			
FAILED PART:	3647135-100	1410	01-253-8073	

DESCRIPTION:

15NOV00: USS Abraham Lincoln reported that the plastic coating to the cable assembly was severely damaged on three missiles. The coating was repaired and the affected missiles were returned to service.

ACTION TAKEN:

28NOV00: NAWC Pt. Mugu stated this problem has been entered for tracking purposes only. This is closing action.

ACTION SUMMARY	ACTIVITY/CODE	ASSIGNMENT	DUE DATE STATUS
	NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE 30NOV00

REFERENCES	IDENTIFICATION	REFERENCE BRIEF
	USS LINCOLN (CVN-72) MESSAGE 220912ZNOV00	PROBLEM REPORT
	NAWC PT MUGU/311000E MESSAGE 280429ZNOV00	REPLY/CLOSING

30-NOV-01

**MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 14963

CLOSED

	NOMENCLATURE	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	GUIDED MISSILE, MAVERICK	3384304-101	1410	01-158-2872	PB69
	GUIDED MISSILE, MAVERICK	3647135-100	1410	01-253-8073	PD63
	GUIDED MISSILE, MAVERICK	3647136-100	6920	01-254-7577	PY15

EI CNTRL NO:

PROB BRIEF : DAMAGED DOME

PROBLEM : Dome cover found missing on missile. Inspection revealed chip on
DESCRIPTION dome.

PREVENTIVE : Adherence to established procedures during ordnance handling
ACTION evolutions will preclude incidents of this nature.

CORRECTIVE : There is no corrective action other than repair of the damaged
ACTION weapon.

	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS	
OCCURRENCES:	VMFA-251	CODR	M09241-01-0021	16AUG01	CLOSED	
	USS ENTERPRISE (CVN-65)	CODR	R03365-01-0016	28JUL01	CLOSED	
	VFA-37	CODR	V09478-01-0023	26FEB01	CLOSED	
	HMM-161	CODR	M09440-00-0002	01JUN00	CLOSED	*
	USS ROOSEVELT (CVN-71)	CODR	V21247-99-0004	16JUL99	CLOSED	*
	USS ENTERPRISE (CVN-65)	CODR	R03365-99-0027	21APR99	CLOSED	*
	USS NIMITZ (CVN-68)	CODR	R03368-97-0011	26OCT97	CLOSED	*
	USS NIMITZ (CVN-68)	CODR	R03368-97-0004	13OCT97	CLOSED	*
	USS NIMITZ (CVN-68)	CODR	R03368-97-0005	13OCT97	CLOSED	*
	USS NIMITZ (CVN-68)	CODR	R03368-97-0006	13OCT97	CLOSED	*
	USS NIMITZ (CVN-68)	CODR	R03368-97-0007	13OCT97	CLOSED	*
	USS NIMITZ (CVN-68)	CODR	R03368-97-0008	13OCT97	CLOSED	*
	USS KENNEDY (CVN-67)	CODR	V03367-97-0005	16AUG97	CLOSED	*
	VFA-137	CODR	V55142-97-0028	12JUL97	CLOSED	*
	USS ROOSEVELT (CVN-71)	CODR	V21247-97-0005	11FEB97	CLOSED	*
	VA-52	CODR	R09283-94-0030	31JUL94	CLOSED	*
	VFA-136	CODR	V55141-94-0806	19JUN94	CLOSED	*
	VFA-147	CODR	R63925-94-0016	11MAY94	CLOSED	*
	USS INDEPENDENCE (CV-62)	CODR	V03362-94-0003	12FEB94	CLOSED	*
	VFA-81	CODR	V09221-93-0038	15DEC93	CLOSED	*
	VA-42	CODR	V09062-93-0004	02AUG93	CLOSED	*

*** ACTION REPORTED IN PREVIOUS PUBLICATION**

30-NOV-01

MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14963

(Continued)

SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
VFA-83	EMR	V09223-92-0022	21AUG92	CLOSED *
VA-95	EMR	R09707-92-0050	23JUL92	CLOSED *
VFA-82	EMR	V09122-92-0005	18JAN92	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : VMFA-251 CODR M09241-01-0021 16AUG01 CLOSED |

END ITEM :	PART/DOC. NO.	FSC	NIIN	NALC
	S/N: 6101212			
FAILED PART:	3647136-100	6920	01-254-7577	PY15
	NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

14AUG01: VMFA-251 reported missile had a pitted dome after being exposed to a rain storm which may have contained hail. Inspection showed the two pitted dome were approximately 1/16" in both depth and width. Weapon turned into USS Roosevelt weapons department awaiting further disposition instructions. Weapon turned into USS Roosevelt weapons department awaiting further disposition instructions. Authorization requested for a one time logistical flight to NAS Jacksonville.

ACTION TAKEN:

20AUG01: NAWC Pt. Mugu granted permission to CVN-71 for one time logistical flight to NAS Jacksonville. Request turn in missile to weapons department. Also, requested NAS Jacksonville weapons department to place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

22AUG01: COMCARAIRWING-1 reported that permission was not received for logistic transport of asset as requested. Asset being held by CVN-71 weapons department.

ACTION :	ACTIVITY/CODE	ASSIGNMENT	DUE DATE STATUS
SUMMARY	NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE 20AUG01

REFERENCES :	IDENTIFICATION	REFERENCE BRIEF
	VMFA-251 MESSAGE 160800ZAUG01	PROBLEM REPORT
	NAWC PT MUGU/311000E MESSAGE 200329ZAUG01	REPLY/CLOSING
	CARAIRWING-1 MESSAGE 221726ZAUG01	TRANSPORT REQUEST

30-NOV-01

MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14963

(Continued)

ACTION : USS ENTERPRISE CODR R03365-01-0016 28JUL01 CLOSED |
(CVN-65)

END ITEM : PART/DOC. NO. FSC NIIN NALC |
S/N: 5101002
FAILED PART: 3384304-101 1410 01-158-2872 PB69
NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

25JUL01: USS Enterprise reported that while doing weapons inspection on missile scratches and pits were noticed on the inside of the dome. Further inspection revealed rivets and metal fragments inside on the bottom of the dome. Awaiting disposition instructions.

ACTION TAKEN:

31JUL01: NAWC Pt. Mugu requested that missile be placed in condition code "F" and shipped to NWS Fallbrook CA for repair. This is closing action.

ACTION : ACTIVITY/CODE ASSIGNMENT DUE DATE STATUS |
SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 31JUL01 |

REFERENCES : IDENTIFICATION REFERENCE BRIEF |
USS ENTERPRISE (CVN-65) MESSAGE PROBLEM REPORT |
281925ZJUL01
NAWC PT MUGU/311000E MESSAGE REPLY/CLOSING |
310029ZJUL01

ACTION : VFA-37 CODR V09478-01-0023 26FEB01 CLOSED |

END ITEM : PART/DOC. NO. FSC NIIN NALC |
3647135-100 1410 01-253-8073 |
S/N: 6101526
FAILED PART: 3647135-100 1410 01-253-8073 PD63
NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

25FEB01: VFA-37 reported that while performing weapons inspection on missile, a crack in the dome was discovered. The missile was turned into the weapons department aboard the USS Harry S. Truman awaiting disposition.

ACTION TAKEN:

01MAR01: NAWC Pt. Mugu requested CVN-75 weapons department to ship the missile to NWS Fallbrook, CA for repair. This is closing action.

30-NOV-01

MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14963

(Continued)

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY	:	NAWC PT MUGU/311000E REVIEW DEFICIENCY			COMPLETE 01MAR01
REFERENCES	:	IDENTIFICATION		REFERENCE BRIEF	
		VFA-37 MESSAGE 261800ZFEB01		PROBLEM REPORT	
		NAWC PT MUGU/311000E MESSAGE		REPLY/CLOSING	
		010129ZMAR01			

30-NOV-01

**MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 15435

CLOSED

	NOMENCLATURE	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	DUMMY GUIDED MISSILE	3384306-100	6920	01-176-6367	2W90
	GUIDED MISSILE, MAVERICK	3647135-100	1410	01-253-8073	PD63

EI CNTRL NO:

PROB BRIEF : SHEARED GROUNDING PIN

PROBLEM DESCRIPTION : This problem addresses incidents in which an A/E37A-T60 Load Drill Trainer was discovered to have a sheared grounding pin on the missile aft hook. Specific cause of the damage could not be ascertained.

PREVENTIVE ACTION : Adherence to established ordnance handling procedures will preclude future occurrences of this nature.

CORRECTIVE ACTION : There is no corrective action other than repair of the deficient weapon.

	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
OCCURRENCES:	VP-8	CODR	V09661-01-0013	18JUL01	CLOSED
	VFA-151	CODR	R09558-01-0024	03MAY01	CLOSED
	VP-26	CODR	V09610-95-0014	29MAR95	CLOSED *
	NAS SIGONELLA	CODR/EIR	N62995-94-0001	28FEB94	CLOSED *
	SFWSPAC	CODR	R35185-93-0053	26APR93	CLOSED *

*** ACTION REPORTED IN PREVIOUS PUBLICATION**

ACTION : VP-8 CODR V09661-01-0013 18JUL01 CLOSED

	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :				
	S/N: 6100406			
FAILED PART:	3647136-100	6920	01-254-7577	PY15
	NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

17JUL01: VP-8 reported missile had a missing grounding pin. This was noticed during the weapons inspection. The load team conducted a FOD walk down with negative results. COMPATRECONWING FIVE states that fleet weapons support team member assigned to the station for possible weapon repair on station.

ACTION TAKEN:

30JUL01: NAWC Pt. Mugu stated this problem has been entered for tracking purposes only. The Maverick Assistant Program Manager Logistics authorized repair to be done on site. This is closing action.

30-NOV-01

MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15435

(Continued)

ACTION : ACTIVITY/CODE ASSIGNMENT DUE DATE STATUS
SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 30JUL01

REFERENCES : IDENTIFICATION REFERENCE BRIEF
VP-8 MESSAGE 181631ZJUL01 PROBLEM REPORT
NAWC PT MUGU/311000E MESSAGE REPLY/CLOSING
300129ZJUL01

ACTION : VFA-151 CODR R09558-01-0024 03MAY01 CLOSED

END ITEM : PART/DOC. NO. FSC NIIN NALC
S/N: 6100319
FAILED PART: 3647135-100 1410 01-253-8073 PD63
NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

30APR01: VFA-151 reported that missile was missing the grounding pin. The missile was turned into weapons department of USS Constellation for disposition instructions.

ACTION TAKEN:

14MAY01: NAWC Pt. Mugu requested USS Constellation weapons department ship the missile to NWS Fallbrook, CA for repair. This is closing action.

ACTION : ACTIVITY/CODE ASSIGNMENT DUE DATE STATUS
SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 14MAY01

REFERENCES : IDENTIFICATION REFERENCE BRIEF
VFA-151 MESSAGE 031511ZMAY01 PROBLEM REPORT
NAWC PT MUGU/311000E MESSAGE REPLY/CLOSING
140029ZMAY01

MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

CLOSED

EI CNTRL NO:

PROB BRIEF : WEAPON DROPPED DUE TO HOIST FAILURE

PREVENTIVE ACTION : As there is no indication that the mishap was the result of improper or careless handling, no preventive action can be prescribed.

CORRECTIVE ACTION : There is no corrective action other than repair of the failed Bomb Hoist and damaged weapon.

	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
OCCURRENCES :	VP-26	CODR/EIR	V09610-01-0008	19APR01	CLOSED
	VMA-223	CODR	M09438-00-0016	14DEC00	CLOSED
	VP-16	CODR	V09229-00-0014	07DEC00	CLOSED
	VA-75	CODR	V09628-96-0106	12AUG96	CLOSED *
	VFA-131	CODR	R63934-93-0052	20OCT93	CLOSED *
	USS ROOSEVELT (CVN-71)	EMR	V21247-93-0005	03AUG93	CLOSED *
	CARAIRWING-8	CODR	V09748-93-0001	05JUN93	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : VP-26 CODR/EIR V09610-01-0008 19APR01 CLOSED

END ITEM :	PART/DOC. NO.	FSC	NIIN	NALC
FAILED PART:	S/N: 6700554 3647135-100	1410	01-253-8073	PD63
	NOMEN: GUIDED MISSILE, MAVERICK			
	S/N: 6700554			

19APR01: VP-26 reported missile was dropped and had dings and gouges on leading edges of control surfaces. Small dents on wing roots near warhead section. VP-26 also requested the costing data for repairs to mishap Maverick missile be forwarded to VP-26 Aircraft Mishap Board for accurate mishap severity classification.

20APR01: NAWC Pt. Mugu requested that missile be placed in condition code "F" and shipped to NWS Fallbrook, CA for repair. Entered into

30-NOV-01

MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15483

(Continued)

AWCAP database for tracking purposes. This is closing action.

27APR01: This was a duplicate of original deficiency report.

30APR01: NAWC Pt. Mugu requested that NAS Sigonella place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. An engineering investigation not considered cost effective for dropped missile when cause of mishap is faulty support equipment.

04JUN01: VP-26 requesting cost data for repairs to mishap on missile.

16JUN01: VP-26 second request that costing data for repairs to mishap on missile be forwarded to VP-26 Aircraft Mishap Board as soon as possible for accurate mishap severity classification.

19JUN01: NAWC Pt. Mugu provided an estimated cost of \$1,700.00 to repair the missile. This is closing action.

ACTION :	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY	NAWC PT MUGU/311000E	REVIEW DEFICIENCY		COMPLETE 20APR01

REFERENCES :	IDENTIFICATION	REFERENCE BRIEF
	VP-26 MESSAGE 191208ZAPR01	PROBLEM REPORT
	NAWC PT MUGU/311000E MESSAGE 200129ZAPR01	REPLY/CLOSING
	VP-26 MESSAGE 271708ZAPR01	DUPLICATE PROBLEM REPORT
	NAWC PT MUGU/311000E MESSAGE 300129ZAPR01	REPLY/CLOSING RESTATED
	VP-26 MESSAGE 041744ZJUN01	COST DATA REQUESTED
	VP-26 MESSAGE 161608ZJUN01	COST DATA SECOND REQUEST
	NAWC PT MUGU/311000E MESSAGE 190129ZJUN01	COST DATA PROVIDED

ACTION :	VMA-223	CODR	M09438-00-0016	14DEC00	CLOSED
-----------------	----------------	-------------	-----------------------	----------------	---------------

	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	3647136-100	6920	01-254-7577	PY15
	NOMEN: GUIDED MISSILE, MAVERICK			
	S/N: 6101072			
FAILED PART:	3647136-100	6920	01-254-7577	PY15
	NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

30NOV00: VMA-223 reported missile was dropped which bent fins and scratched the side of the guidance section.

30-NOV-01

**MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 15483

(Continued)

ACTION TAKEN:

27FEB01: NAWC Pt. Mugu requested VMA-223 place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION :	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY	NAWC PT MUGU/311000E	REVIEW DEFICIENCY		COMPLETE 27FEB01

REFERENCES :	IDENTIFICATION	REFERENCE BRIEF
	VMA-223 MESSAGE 141310ZDEC00	PROBLEM REPORT
	NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
	270029ZFEB01	

ACTION :	VP-16	CODR	V09229-00-0014	07DEC00	CLOSED
-----------------	--------------	-------------	-----------------------	----------------	---------------

	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	3647136-100	6920	01-254-7577	PY15
	NOMEN: GUIDED MISSILE, MAVERICK			
	S/N: 6101102			
FAILED PART:	3647136-100	6920	01-254-7577	PY15
	NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

07DEC00: VP-16 reported that the hoist operator attempted to lower the weapon by depressing the brake handle on the HLU-196 hoist. When the hoist operator depressed the brake handle, the weapon fell freely onto the trailer resulting in damage to the missile.

ACTION TAKEN:

14DEC00: NAWC Pt. Mugu recommended NAS Jacksonville, FL load missile on aircraft platform to do a thorough inspection and load check to ensure no additional damages other than what was reported. If missile passes all checks a replacement panel will be sent to replace the damaged panel. If missile fails check out request place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. Entered into AWCAP database for tracking purposes. This is closing action.

20DEC00: Phone con between NAWC and NAS Jacksonville confirmed that after inspection and load checks, there was no additional damage done to the missile other than what was reported. A request, via email, went out to NWS Fallbrook for them to send the replacement panel to NAS as soon as possible. Panel was shipped on 22Dec00 and received by NAS Jacksonville on 27Dec00.

ACTION :	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY	NAWC PT MUGU/311000E	REVIEW DEFICIENCY		COMPLETE 20DEC00

30-NOV-01

MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15483

(Continued)

REFERENCES : IDENTIFICATION

VP-16 MESSAGE 071800ZDEC00

NAWC PT MUGU/311000E MESSAGE

141029ZDEC00

NAWC PT MUGU/311000E EMAIL 20DEC00

REFERENCE BRIEF

PROBLEM REPORT

REPLY/CLOSING

REPLACEMENT PANEL SHIPPED

30-NOV-01

MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15644

CLOSED

	NOMENCLATURE	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	GUIDED MISSILE, MAVERICK	3384304-101	1410	01-158-2872	PB69
	GUIDED MISSILE, TRAINING	3384305-100	6290	01-254-7577	3W70
	GUIDED MISSILE, MAVERICK	3647135-100	1410	01-253-8073	PD63
	GUIDED MISSILE, MAVERICK	3647136-100	6920	01-254-7577	PY15

EI CNTRL NO:

PROB BRIEF : WEAPON DAMAGED DURING HANDLING

PROBLEM : This problem addresses incidents in which weapons were damaged
DESCRIPTION during flight deck or flight line ordnance handling evolutions, and includes incidents of weapons being struck by tow tractors and incidents involving the overturning of weapons skids.

PREVENTIVE : There is no preventive action other than adherence to established
ACTION procedures when handling/transporting weapons.

CORRECTIVE : There is no corrective action other than testing/repair of the
ACTION damaged weapons.

	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
OCCURRENCES:	MALS-31	CODR	M09131-00-0105	04JAN01	CLOSED
	VP-4	CODR	R09623-99-0010	30JUL99	CLOSED *
	USS ENTERPRISE (CVN-65)	CODR	R03365-98-0002	22MAY98	CLOSED *
	USS SEATTLE (AOE-3)	CODR	V05848-98-0001	07MAY98	CLOSED *
	NAS WHIDBEY IS	CODR	N00620-98-0001	23MAR98	CLOSED *
	VP-46	CODR	R09632-98-0002	09DEC97	CLOSED *
	VMFA-312	CODR	M09253-96-0008	19FEB96	CLOSED *
	VMFA(AW)-121	CODR	M09257-95-0039	17OCT95	CLOSED *
	VFA-192	CODR	R09076-95-0009	04OCT95	CLOSED *
	NAS WHIDBEY IS	CODR	N00620-95-0003	06APR95	CLOSED *
	VFA-37	CODR	V09478-94-0046	01DEC94	CLOSED *
	VFA-131	EMR	R63934-94-0025	30JUL94	CLOSED *
	VFA-131	CODR	R63934-94-0001	23FEB94	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : MALS-31 CODR M09131-00-0105 04JAN01 CLOSED

	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	3384305-100	6290	01-254-7577	3W70
	NOMEN: GUIDED MISSILE, TRAINING			
	S/N: 5000431			
FAILED PART:	3384305-100	6290	01-254-7577	3W70
	NOMEN: GUIDED MISSILE, TRAINING			

30-NOV-01

MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15644

(Continued)

DESCRIPTION:

13DEC00: MALS-31 reported that missile hatch cover on front section was dented inward. The missile is being held awaiting disposition.

ACTION TAKEN:

15FEB01: NAWC Pt. Mugu requested that MALS-31 place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY	:	NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	15FEB01

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
	:	MALS-31 MESSAGE 040800ZJAN01	PROBLEM REPORT
	:	NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
	:	150229ZFEB01	

30-NOV-01

MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16308

CLOSED

END ITEM	NOMENCLATURE	PART/DOC. NO.	FSC	NIIN	NALC
:	GUIDED MISSILE, MAVERICK	3647136-100	6920	01-254-7577	PY15

EI CNTRL NO:

PROB BRIEF : SHATTERED IR DOME

PROBLEM : Missile IR dome was shattered by forklift.
DESCRIPTION

PREVENTIVE : There is no preventive action at this time.
ACTION

CORRECTIVE : There is no corrective action at this time.
ACTION

OCCURRENCES:	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
	VP-45	CODR	V09665-00-0025	30OCT00	CLOSED
	USS BOXER (LHD-4)	CODR	R21808-97-0001	15JUN97	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : VP-45 CODR V09665-00-0025 30OCT00 CLOSED

END ITEM	PART/DOC. NO.	FSC	NIIN	NALC
:	S/N: 6100858			
FAILED PART:	3647135-100	1410	01-253-8073	PD63
	NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

28OCT00: VP-45 reported missile infrared glass dome was shattered by Aero-51C trailer hitch. Investigation revealed missile was covered with a tarp and centered on Aero-51C trailer. Trailer was parked along edge of flight line perpendicular to ramp vehicle taxiway for three days with trailer hitch in the down position. Missile turned into NAS Sigonella weapons department awaiting disposition.

ACTION TAKEN:

20NOV00: NAWC Pt. Mugu requested NAS Sigonella weapons department place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION SUMMARY	ACTIVITY/CODE	ASSIGNMENT	DUE DATE STATUS
:	NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE 20NOV00

30-NOV-01

MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16308

(Continued)

REFERENCES : IDENTIFICATION

VP-45 MESSAGE 301200ZOCT00
NAWC PT MUGU/311000E MESSAGE
200629ZNOV00

REFERENCE BRIEF

PROBLEM REPORT
REPLY/CLOSING

30-NOV-01

**MAVERICK ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 16946

CLOSED

EI CNTRL NO:

PROB BRIEF : MISSILE DAMAGED DUE TO WATER CONTAMINATION

PROBLEM DESCRIPTION : This problem addresses an incident in which a pipe was capped off where eductor discharge pipe had been previously removed. Cap blew off, allowing water to flood magazine. Weapons were rolling stock and were approximately 75% submerged.

PREVENTIVE ACTION : All personnel should secure weapons magazines aboard ship.

CORRECTIVE ACTION : There is no corrective action at this time.

	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
OCCURRENCES:	USS ENTERPRISE (CVN-65)	CODR	R03365-01-0013	21JUN01	CLOSED

ACTION :	USS ENTERPRISE (CVN-65)	CODR	R03365-01-0013	21JUN01	CLOSED
-----------------	-----------------------------------	-------------	-----------------------	----------------	---------------

	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	S/N: 6101118, 6101037, 6101086			
FAILED PART:	3647136-100	6920	01-254-7577	PY15
	NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

17JUN01: USS Enterprise reported that three missiles were submerged in saltwater/sewage due to a cap blowing off of a pipe. Awaiting disposition instructions.

ACTION TAKEN:

27JUN01: NAWC Pt. Mugu requested USS Enterprise weapons department place missiles in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY	NAWC PT MUGU/311000E	REVIEW DEFICIENCY		COMPLETE 27JUN01

REFERENCES :	IDENTIFICATION	REFERENCE BRIEF
	USS ENTERPRISE (CVN-65) MESSAGE 211308ZJUN01	PROBLEM REPORT
	NAWC PT MUGU/311000E MESSAGE 270229ZJUN01	REPLY/CLOSING